

EUV mask and blanks development at HOYA

T. Shoki, T. Kinoshita, M. Hosoya, N. Sakaya, H. Kobayashi,
Y. Usui, R. Ohkubo, and O. Nagarekawa

Electronics Development Center, HOYA CORPORATION

Outline

- **EUV mask structure at Hoya**
- **Technical issues of EUV blanks and mask**
- **Blanks characteristics**
 - Multilayer defect
 - Absorber stack properties
- **Mask characteristics**
 - Dry etching damage to multilayer
 - Absorber repair
 - Absorber stack patterning
 - DUV inspection images
 - EUV contrast
- **Summary**


HOYA EUV mask

LR-TaBN absorber


LR: Low Reflectivity

Amorphous material
High stress stability
High EUV absorption

CrN buffer layer



Structure of EUV mask



40 bi-layers


- **LR-TaBN absorber**
 - The continuous layer with low optical reflectivity layer
 - Low reflectivity of 5% at 257 nm to obtain higher inspection contrast
- **CrN buffer layer**
 - Acts as etch stop layer during absorber etching and protect layer during absorber repair process



Some technical issues must be solved.


Technical issues of EUV blanks

Process flow




ML (40 bi-layers) and Si capping layer deposition (by IBD)


Reflectivity: NewSUBARU BL10




Cleaning & inspection



CrN buffer and LR-TaBN absorber deposition (by magnetron sputtering)



Cleaning & inspection



EB resist coating and baking

Technical issues

Zero defect ML (for 50 nm sizes)


High EUV reflectivity: >65%

Low stress: <200 MPa



High cleaning durability

Technical issues of EUV mask



Process flow




EB writing and
resist developing



Absorber etching with Cl_2
gas and resist stripping



Buffer layer etching with
 Cl_2/O_2 mixed gases



Mask inspection (DUV/257 nm)

Technical issues

Mask performance
IP and CD

Damage less repair
process

Absorber repair with
high etch selectivity

Thinner buffer

Mask inspection with
high contrast

Absorber patterning
with vertical side wall

High dry etching durability to ML

High EUV reflectivity on mask

ML defects reduction

Total defects on ML blanks measured by M1320




Fig. Progress in ML defect reduction

0.03 def/cm² @150 nm





Fig. Defect map of ML blank



Further reduction in ML defects will be performed.

Properties of LR-TaBN/CrN blanks

Stress and roughness of the blanks




Fig. Flatness change in 142-mm sq. and roughness in 10 μm after CrN deposition and then after LR-TaBN deposition.

Low stress: <200 MPa
Smooth surface: 0.25 nm Rms

Cleaning durability of LR-TaBN




Fig. Optical reflectivity spectra of LR-TaBN film before and after the cleaning process.

High cleaning durability
against conventional cleaning

Dry etching damage to ML blanks

--Reflectivity change--

Dry etching selectivity of CrN buffer to Si capping layer is nearly infinite







Fig. Relationship between the increased thickness on the capping layer and reflectivity change after three etching processes.

 The mask featured reflectivity loss of 1.5-5% due to an increase of the capping layer.

Dry etching damage to ML blanks

--Compositional analysis of Si capping layer--


Initial



(a) XPS depth profile of original Si capping layer

Additional silicon oxide layer

After CrN buffer etching




(b) XPS depth profile of Si capping layer after CrN buffer etching



SiO₂ layer is formed on the original Si capping layer during CrN buffer etching.

Dry etching damage to ML blanks

--TEM analysis on Si capping layer--




TaBN absorber (90 nmt)
CrN buffer layer (10 nmt)
Mo/Si multilayer


After CrN buffer etching

Additional oxide layer (3 nmt)


After HF treatment



Cap-Si (7 nmt)



In a diluted HF
for 120 sec.



➡ The additional SiO_2 layer is removed without structural damaging by HF treatment.

EUV mask reflectivity

ML blank (40 bi-layers)

CrN buffer etching

HF treatment




Fig. Peak reflectivity, reflectivity uniformity and centroid wavelength for starting blank and mask after buffer layer etching and HF treatment.




Fig. Reflectivity spectra for starting blank and mask after buffer layer etching and HF treatment.

 Peak reflectivity of around 65% was obtained on the mask.

New capping layer with higher dry etching durability

New capping layer





Fig. TEM image of ML blanks with new capping layer.



- Simple ML structure
 - Produced from only Si and Mo targets.
- High durability against CrN etching

➡ EUV mask with new capping layer showed no change in reflectivity after CrN etching process.

Dry etching damage to ML




Fig. Peak reflectivity of ML with Si cap layer and ML with new cap layer before and after CrN etching.


Etch performance in EB repair

Etch of 70 nmt LR-TaBN absorber



Courtesy of NaWoTec on the EB repair



Patterning process of EUV mask



EB writing and
resist developing





EB resist: Posi type CAR
LR-TaBN: 90 nmt
CrN: 10 nmt




Absorber etching
and resist stripping



LR-TaBN absorber etching
(by ICP-RIE)
Etching gas: Cl_2
Pressure: 0.1 Pa
Selectivity to CrN: >20



Buffer layer
etching





CrN buffer layer etching
(by ICP-RIE)
Etching gas: $\text{Cl}_2 + \text{O}_2$
Pressure: 0.1 Pa
Selectivity to Si: >50

EUV masks were produced for evaluation of pattern images and mask inspection.

Cross sectional pattern images

EUV test mask including L&S patterns and hole patterns

Line and space patterns



Pattern structure



LR-TaBN
(90nm)

CrN (10nm)

Si cap (11nm)


ML (~280nm)
[40 bi-layers]

Hole patterns




257nm DUV inspection images

EUV mask structure




Optical contrast on the mask



Inspection image at TeraScan 257 nm

Programmed defect mask
(Patterns with a feature size of **240 nm**)




The EUV mask showed good contrast

Courtesy of KLA-Tencor on the TeraScan DUV inspection system


EUV contrast on EUV mask

CrN buffer layer

Etch depth during EB repair: <1 nm
Etch depth during TaBN etch: <2 nm



CrN buffer: 5 nmt
LR-TaBN: 90 nmt




	Present mask	Target (for 45 nm node)
Mask contrast	98.2%	>97%
Aspect ratio	0.52	<1.3

EUV reflectivity spectra

ML: 11nmt-Si/40-bilayers

CrN: 5 nmt

LR-TaBN: 90 nmt





Summary

LR-TaBN absorber (90 nmt)

CrN buffer layer (5 nmt)

**EB based repair
DUV mask inspection
(TeraScan/257 nm)**



EUV blanks performance

- Low reflectivity TaBN absorber: <5% at 257nm
- Smooth surface: ~0.25 nm Rms
- Low stress: <200 MPa
- High EUV absorption: 95 nmt for 98% contrast
- Fine patterning capability: 200 nm width on mask
 - nearly vertical side wall
- High etching selectivity (TaBN/CrN): 595
 - using EB repair process
- High dry etching durability to ML

EUV mask performance

- High inspection contrast
- Less LER
- Less IP
- Low aspect ratio: 0.52
- Precise mask (CD control)
- Damage less repair
 - using EB repair process
- High EUV reflectivity

Next action

- To evaluate mask IP, CD and LER
- To perform defect reduction in ML blanks